



Worksheet

Tue Jun 21, 2005 11:05am

Inspection Number	303764906
Opt. Insp. Number	1746

Establishment Name	Paras Concrete Contractors				
Type of Violation	S Serious	Citation Number	01	Item/Group	001
Number Exposed	2	No. Instances	1	REC	
Std. Alleged Vio.	1926.0652(a)(1)(ii)				

Abatement Period	MultiStep Abatements			Final Abatement	Action Type/Dates
	PPE Period	Plan	Report		
0				Corrected During Inspection	
Abatement Documentation Required		N	Date Verified		

Substance Codes	
-----------------	--

AVD/Variable Information:

29 CFR 1926.652(a)(1)(ii): In excavations less than 5 feet (1.52m) in depth had not been examined by a competent person to ensure there is no indication of a potential cave-in:

a) At the jobsite, where an employee worked within the excavation measuring 3'10" in depth while squaring the edges the employee was exposed to a potential cave-in and no competent person had inspected the excavation.

Penalty Calculations				Adjustment Factors			Proposed Adjusted Penalty
Severity	Probability	Gravity	GBP	Size	Good Faith	History	
M Medium	G Greater	05	3500.00	0	15	10	2625.00
Repeat Factor		0					

Employee Exposure:					
Occupation	competent person			Employer	
Nr of Employees	2			Duration	Frequency
Employee Name	EX: 7C				
Address				Phone	EX: 7C
Occupation	Laborer			Employer	
Nr of Employees	2			Duration	Frequency
Employee Name	EX: 7C				
Address				Phone	EX: 7C

Instance Description: A. Hazard B. Equipment C. Location D. Injury/Illness E. Measurements

4. Date/Time
04/19/05

20. Instance Description - Describe the following:

- a) Hazards-Operation/Condition-Accident Caught in. The CSHO observed employees working within an excavation measuring 3'10". The employees were on their bellies crawling between two vertical rebar mats that were placed within the excavation. Employees were wearing hard hats. Based on employee interviews it was determined the employees were using hand tools to square the edges of the excavation in preparation of the concrete pour. Based on an interview with Mr. Miller it was determined that *EX:7C* was the competent person onsite. In an interview with *EX:7C* it was determined he did not meet the requirements of a competent person for trenching/excavation because he did not know soil types, how to determine soil types, sloping, or the duties of a competent person.
- b) Equipment A competent person did not examine the excavation.
- c) Location Jobsite
- d) Injury/Illness Broken bones, potential organ damage due to crushing.
- e) Measurements Excavation depth: 3'10".

21. Photo Number	Location on Video

23. Employer Knowledge : *EX:7C* recognized the hazard when discussed.

24. Comments (Employer, Employee, Closing Conference) :

25. Other Employer Information : The employees were removed from the excavation.

26. Classification:				
Serious	Knowledge	S or O	Repeat?	Willful?
y	y	s	n	n

First Repeat	Second Repeat	Repeat Penalty

Event Date	Event Code	Action Code	Citation Type	Penalty	Abate Date	Final Order
	Z Add transaction	A Add	S Serious	2625.00		